

10/606,787.

CDC



Docket No.: 239689US3X

OBLON  
SPIVAK  
McCLELLAND  
MAIER  
&  
NEUSTADT  
P.C.  
  
ATTORNEYS AT LAW

COMMISSIONER FOR PATENTS  
ALEXANDRIA, VIRGINIA 22313

RE: Inventor: Takashi HONDA, et al.

Patent No.: 7,035,054

Issued: April 25, 2006

Group Art Unit: 2652

Examiner: RENNER, CRAIG A

For: MAGNETIC HEAD APPARATUS WITH LOAD  
BEAM FLOATING STRUCTURE

SIR:

Attached hereto for filing are the following papers:

**REQUEST FOR CERTIFICATE OF CORRECTION**  
**CERTIFICATE OF CORRECTION FORM PTO 1050**

Our check in the amount of \$0.00 is attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R. 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. A duplicate copy of this sheet is enclosed.

Certificate  
MAY 8 2006  
of Correction

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND,  
MAIER & NEUSTADT, P.C.

*Joseph Scafetta Jr.*


C. Irvin McClelland  
Registration No. 21,124

Joseph Scafetta, Jr.  
Registration No. 26,803

Customer Number

22850

Tel. (703) 413-3000  
Fax. (703) 413-2220  
(OSMMN 03/06)



DOCKET NO.: 239689US3X/smc

MAY 04 2006

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

APPLICATION OF: Takashi HONDA, et al.

PATENT NO.: 7,035,054

GROUP: 2652

ISSUED: April 25, 2006

EXAMINER: RENNER, CRAIG A

FOR: MAGNETIC HEAD APPARATUS WITH LOAD BEAM FLOATING STRUCTURE

**REQUEST FOR CERTIFICATE OF CORRECTION**

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE  
ALEXANDRIA, VA 22313-1450

SIR:


The following is a Request for Certificate of Correction in Serial Number 10/606,787, now U.S. Patent Number 7,035,054.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the U.S. Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the U.S. Patent and Trademark Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND,  
MAIER & NEUSTADT, P.C.

  
C. Irvin McClelland  
Registration No. 21,124

Joseph Scafetta, Jr.  
Registration No. 26,803

Customer Number

22850

Tel. (703) 413-3000  
Fax. (703) 413-2220  
(OSMMN 03/06)

MAY 8 2006

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : **7,035,054**  
DATED: **Apr. 25, 2006**  
INVENTOR(S): **Honda et al.**

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (54), and Column 1, the Title is incorrect. Item (54) and Column 1 should read:

-- (54) **MAGNETIC HEAD APPARATUS WITH LOAD  
BEAM FLOATING STRUCTURE** --

Mailing address of sender:

Patent No. **7,035,054**

Customer Number

**22850**

No. of add'l copies  
@ .30 per page

Tel. (703) 413-3000  
Fax. (703) 413-2220  
(OSMMN 03/06)



**MAY 8 2006**

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : **7,035,054**

DATED: **Apr. 25, 2006**

INVENTOR(S): **Honda et al.**

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (54), and Column 1, the Title is incorrect. Item (54) and Column 1 should read:

-- (54) **MAGNETIC HEAD APPARATUS WITH LOAD  
BEAM FLOATING STRUCTURE** --

Mailing address of sender:

Patent No. **7,035,054**

Customer Number

**22850**

No. of add'l copies  
@ .30 per page

Tel. (703) 413-3000  
Fax. (703) 413-2220  
(OSMMN 03/06)



APR 25 2006